



BMW 576 Warning Insert
M-MIS-90254

warning !!

You must make sure that the CODE PLUG on the original board is good before transferring it to the new board!!

If a bad plug is inserted on this remanufactured unit damage may occur and the warranty will be void.



Location for CODE PLUG

**We buy electronic automobile cores!
For information on core purchasing or warranty issues, call (800) 668-8843 x 32**