

(189) Instructions

THIS UNIT FITS ONLY: THIS CRUISE HAS THE DECELERATE OPTION.

M3	07/89 - 12/90
325i	07/89 - 04/91
325iC	07/89 - 10/92
325e	10/83 - 6/88
325iX	07/89 - 01/91

Perform steps 1 - 2 prior to installation.

1. Turn off ignition and disconnect Cruise Control Amplifier.
2. (+) pin 13 → (-) pin 25 = between 7-15 ohms, **IF NOT, STOP AND REPLACE CRUISE CONTROL ACTUATOR.**

THREE YEAR WARRANTY

TROUBLESHOOTING NOTES

ORIGINAL UNIT PROBLEM

Symptoms	Test/Suspect Problems	Solution
Unit will not engage.	Faulty Cruise Control Actuator. (+) pin 13 → (-) pin 25 = 7-15 ohms	Replace Cruise Control Actuator.

NEW UNIT PROBLEMS

Symptom	Test/Suspect Problem	Solution
Cruise Control will not engage.	Blown Fuse.	Replace fuse.
	between pins and connector on Cruise Control Amplifier.Poor connection	Check, clean and crimp connectors as needed.
	Burned out brake lamps.	Replace brake lamps.
	Faulty vehicle Speed Sensor.	Check and repair.