

Instructions (344 & 34401)

THIS UNIT FITS ONLY:

M5	09/90 - 09/93	735i	8/86 - 6/92
525i	01/88 - 12/95	735iL	1/88 - 7/92
530i	11/92 - 12/95	740i	6/92 - 4/94
535i	01/88 - 02/93	740iL	6/92 - 4/94
540i	11/92 - 02/95	750iL	1/87 - 3/94
730i	06/92 - 03/94		

Prior to installation, verify this is the correct part for your application.

Ensure that light assembly is not full of water, if so it will disable unit.

IF NOT, WARRANTY IS VOID

GENERAL TROUBLESHOOTING NOTES

NEW UNIT PROBLEMS

Symptom	Test/Suspect Problem	Solution
If Check Control comes on display of instrument cluster.	No power to light control module.	Check all fuses.